

LetB

Time advancement fix



This tutorial shows how to fix time advancement of LetB v2 clock with software update.

Requirements:


- Computer with Windows OS.
- Programmer (provided)
- Mini USB cable

To solve the issue software update is required. To proceed follow the next steps.

1. Disconnect LetB from the power supply
2. Pry open black holders at the back of the clock (Pic 1.)
3. Remove the main board (hold with a piece of glue) – be careful not to break any connections to external elements. (Pic 2.)




Pic 1.




Pic 2.

4. Connect programmer (Pic 3.) to the board as shown on the Pic 4.




Pic 3.



Pic 4.

5. Connect programmer to the computer with USB cable and wait while it is being installed.
6. Open XLoader.exe app from the XLoader folder and choose following options shown on Pic 5.



Choose the right hex file for your LetB version. NOTE: COM port number may vary depending on your computer setup.

7. Click **Upload** button and wait for the software to be uploaded.
8. Now your LetB has the newest software with fixed time advancement issue.
If you are using LetB PRO you can further adjust time via mobile app.
9. Follow the steps in reverse to assembly the clock.